Louis &, Savoil
29 Killsdale Rd

Holbrook. Mass.
02343
-617-767-1638

WOLFEBORO, N. H 03894

DATE

SIGNED

SEND PARTS 1 AND 3 INTACT-PART 1 WILL BE RETURNED WITH REPLY

RM-87

RETURN TO ORIGINATOR

Speed Letter。

ToEllis Miller W1IIQ	FromL. Savoie	
	29 Hillsdale Rd.	
Wolfeboro, N.H. 03894	Holbrook, Ma. 02343	
Subject IC 230 Repairs	617-767-1638	
-No 96 10 FOLD	- /	
MESSAGE	Date 9/15 19 78	
Mr. Miller: I received the IC230 today and have had an opportunity to evalate		
it for repair. You were correct in your asumption that someone has had their hands		
into the sensitive innards of this unit. They have! There were two shorts in the		
cabling along the sides of the unit - probably happened with repeated taking off the		
covers and jamming them back on without respect to the pinch fit nature of the case.		
the Shorts caused some burnouts of components in the regulated power supply unit:		
the +9v reg is burned out, and so is the ±9v reg for transmit funtions. The pll		
unit is imoperative and has two open transmstors (probably cause with the +@v rec		
voltage shorted through that section of the unit; this will require some rebuilding		
of the VCO, Mixer and CO module. Mainly replacing burned or open components or		
transistors. The final transistors are ok; most of the problems are in the voltage		
-No.10F\$65 dollars. What is your pleasure? Signed Free Source		
(Please respond via either this speed letter or by phone after % 7:00 PM, Tnx)		
REPLY	Date1919	
Repair authorized 9/20/78		
Phone calls to Low avoil 617-767-1638		
Bills Lintto: 11. T. Leach 9/28/78. Vor payment.		
-No 9&10 FOLD		
	Signed	

Speed Letter.

From Ellis Miller WIII0	To L. Savoie	
	29 Hillsdale Rd.	
Welfshore N H 0790L	Holbrook, Ma. 02343	
Wolfeboro, N.H. 03894 Subject IC 230 Repairs	6/7-767-1638	
Subject -No.9 & 10 FOLD	0,, 0,, 1008	
MESSAGE	Date 9/15 1978	
Mr. Miller: I received the IC230 today	and have had an opportunity to evalue	
it for repair. You were correct in your a	sumption that someone has had their hands	
into the sensitive invards of this unit.	They have! There were two shorts in the	
cabling along the sides of the unit - prob	ably happened with repeated taking off the	
covers and jamming them back on without re	spect to the pinch fit nature of the case.	
the Shorts caused some burnouts of components in the regulated power supply unit:		
the +9v reg is burned out, and so is the ±	9v reg for transmit funtions. The pll	
unit is imperative and has two open transpitors (probably cause with the +9v rec		
voltage shorted through that section of th	e unit; this will require some rebuilding	
of the VCO, Mixer and CO module. Mainly r	eplacing burned or open components or	
transistors. The final transistors are ok	; most of the problems are in the voltage	
-No. 9 Folio and current regulators and the PLL circuitry. Estimate to repair 12 between 190 and		
(Please respond via either this speed lett	the state of the s	
NEFL!	Date19	
	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
	-//-	
Repair authorized	9/20/78	
Phone Calles to alexa	ichie	
Ken Le		
Pete	Colbath. Confirmed.	
	3-Hu.	
-No.9810FOLD	The state of the s	
The state of the s	Signed	